

Wonderwood Connector Bridge Post-Tensioning Tendons Investigations and Phase 1 Repair

Teddy Theryo, Ivan Lasa, Marcelino Aguirre, Daniel Rosa



Learning Objectives

- Understanding the processes of post-tensioned bridges durability investigations
- Learning the application of Non-Destructive Evaluation (NDE) Method
- Developing structural evaluations prior to repair strategy
- Implementing repair concept to repair plans
- Learning how to repair soft grout
- Learning new technology (drying and impregnation of corrosion inhibitor) through strands interstitials spaces in protecting strands corrosion



Presentation Outline

- 1. Background
- 2. PT Tendons Investigations
- **3. Repair Strategy**
- 4. Phase 1 Repair Construction
- 5. Closing



Background

Bridge Description

- **Bridge No. 720677**
- Wonderwood Connector Bridge is located over the Inter-coastal Waterway on SR 166, north east of Jacksonville, FL
- The total bridge length is 3584' and 90'-9" wide deck consisted of 8 lines of prestressed concrete I girders.
- The focus of this presentation is the three-span continuous Post-tensioned spliced girder main span bridge of 197'-250'-197' (total length of 644')



Construction Information

- Construction date: 2002 2004
- PT system: VSL (old system)
- PT duct: Galvanized corrugated metal duct
- Grout: Sika Cable Grout





Main Spliced Girder Unit Elevation View





Typical Cross Section





Typical Section





Notes: Due to geometry control issues that arose during construction, counterweights were added in the side spans.

FDOT

PORTATION

Beam	Tendon 1	Tendon 2	Tendon 3	Tendon 4	Total
1	15	15	19	18	67
2	15	15	19	18	67
3	15	15	19	19	68
4	15	15	19	16	65
5	15	15	19	18	67
6	15	15	19	19	68
7	15	15	18	18	66
8	15	15	19	18	67

Note: Tendon sizes range from 15-0.6" to 19-0.6" strands



Initial PT Investigations

Scope: To obtain some grout samples for chloride test

1st inspection : April 16, 2012 to May 4, 2012 2nd inspection : July 16, 2012 to August 10, 2012

Report Findings

- 1. Metal duct corrosion
- 2. Strands corroded (no failed strands found)
- 3. Putty-like grout (5 samples from girders), high moisture
- 4. Soft, chalky grout (6 samples from girders)
- 5. Chloride contents : 0.01 to 0.04% by weight of cement. [limit 0.08%]
- 6. Moisture Content: 50% to 75%



Grouting Problems during Construction

- Beam 1 T3: Cap and hose blew out
- Beam 1 T4: Grout leaked at closure, anchor head cracked, stopped grouting at I port, grout set (incomplete grouting), pumped grout from the other end.
- Beam 4 T3: While grouting T3, found leakage at upstream closure @ P10 haunch and grout crossed over to T4,Tube broke off at I port, flushed out T3, LE was empty. T4 was blocked.
- Beam 4 -T4: blockage found in the center part of mid-span; water found from pier 9 to 10; closure pour spall from top flange into the web; grouting was done from both ends.

Note: Missing grouting data of all beams T1 and T2.





PT Tendons Investigations Legend Putty Grout Thick Black Material Soft and Chalky Grout Hard Grout Ducts Corroded Ducts Location of Strands 4999

Severe Strand CorrosionModerate Strand CorrosionMinor Surface Corrosion

Findings in graphical form Courtesy of D2 DSMO





PT Tendons Investigations Legend Putty Grout Thick Black Material Soft and Chalky Grout Hard Grout Ducts Corroded Ducts Location of Strands مممه Severe Strand Corrosion 000 ₩ Moderate Strand Corrosion 9999 Minor Surface Corrosion

Findings in graphical form Courtesy of D2 DSMO





Conditions while grout samples were being collected (note black material under the putty like grout).

Tendon 2 in Girder 8 at Pier 11

Corrosion on the inside surface of the duct that was in contact with putty like grout (left photograph) and no corrosion on wires that were in good grout.



FDOT TRANSPORTATION SYMPOSIUM









Strands with moderate corrosion and severe corrosion (before and after cleaning off corrosion products with a wire brush)





Failed corroded strand

Notes: The failed corroded strand was discovered during the repair when the contractor was trying to obtain grout sample for moisture test.



Follow-up Investigation (3rd Investigation)

Time frame: September 22, 2014 to October 14, 2014 Method: Sonic / Ultrasonic Impact Echo NDE and Ground Penetrating Radar (GPR) was used to locate the tendon locations.

Primary goal: To map areas of soft grout and voids for all tendons for repair plans.



- Confirmed the previous findings from the 1st and 2nd investigations.
- Discovered voids of 20 ft. long duct filled with water (Girder 8, Span 11, Tendon 3). The water could be from run-off from the deck through pour-back over the pier based on pressure test. or bleed water. The PH levels of test result showed indicative of bleed water.
- 3% (400 ft.) of approximately 13,555 feet tendon length subjected to impact echo, indicated the presence of soft grout and / or voids.
- □ 30% filled with hard grout.

Report Findings

- 67% have a thin rim of soft grout surrounding hard grout (1/16" to ¼ " thick; ¾" thick in localized areas).
- The thin rim of soft grout consisted of thin rim of brittle grout surrounding hard grout, powder grout surrounding hard grout, putty grout sounding hard grout and duct corrosion.
- 87 locations of small holes in the duct were drilled for inspection verifications and borescope.





PHOTOGRAPH 1: Passing a radar antenna over a web tendon



FDOT

TRANSPORTATION



Figure 5: Samples of Time Domain and Frequency Domain data



8,57,99.

8,48 99.1

8.16 99.0

7.77 99.1

8,24.99.0

Photo shows application a projectile impact energy source over web tendon

PT Tendons Investigations





Figure 5A. Collection of a water sample at the drilled hole at NDT Station No. 19.





Figure 15B. Photograph inside the drilled hole at NDT Station No. 193 (S11-G4-T2).

FDOT

TRANSPORTATION SYMPOSIUM



PHOTOGRAPH 6: Temporary protection plug



PHOTOGRAPH 7: Soapy water bubbles around patch in the deck



PHOTOGRAPH 8: Soapy water bubbles around cracks in the deck

FDOT

TRANSPORTATION SYMPOSIUM

Repair Strategy

Based on the three investigation reports, FDOT D2 DSMO Tasked Parsons Brinckerhoff (WSP) to study a repair strategy for Wonderwood Connector bridge.

Objective:

Evaluate the structural behavior and capacity of the main span unit in case of tendon deficiency.

Scope:

- Review existing plans, inspection reports, and construction documentation.
- Compute loads and time-dependent effects to determine service and ultimate load combinations. Check stresses and ultimate capacity assuming no structural deficiencies.
- Evaluate four tendon failure scenarios and determine impact on service and ultimate limit states.



Repair Strategy

Initial Phase I Repair Recommendations

Repair the existing tendons with deficiencies, such as grout voids, duct with water and soft-grout.

- *Remove soft grout
- Fill voids with vacuum grouting
- Apply Vector's Impregnation repair method for tendons with soft grout, including drying of the grout

Foot Notes:

- * Soft grout removal mock-up was not successful during Lab Testing, and later changed to drying of the soft grout
- The Vector's Impregnation method was Lab tested to improve process
- Technical Special Provisions were developed for both grout vacuum injection and Drying plus Impregnation



Repair Strategy / Lab Testing

Soft grout removal mock-up test at FDOT Structural Laboratory in Tallahassee









Repair Strategy / Lab Testing

Soft grout removal mock-up test at FDOT Structural Laboratory in Tallahassee







Repair Strategy / Lab Testing

Mock-up Test for Soft Grout removal

Conclusion: Unsuccessful

Results - Loose grout clogged outlet port

Mock Up- 5 Soft Grout Recipe Scenarios



Results - Soft grout remained and water migration to hard grout locations



Rotation Nozzle Hydro-blasting



Hydro-blasting









Repair Strategy Soft grout dehumidification / drying mock-up test at FDOT Structural Laboratory in Tallahassee









Repair Strategy Lab Testing

Mock-up testing for drying soft grout



Two – 32 ft. tubes with humidity sensors continuously dried for 90 days



Repair Strategy Lab Testing

Results

- Drying decreased moisture content
- Vacuum assisted drying shortened drying time
- A continuous power source is needed
- Humidity probes are unreliable after exposure to water



Figure 6 Comparison of moisture content for drying and control specimens 2

FDOT

Final Phase 1 Repair Strategy After Lab Testing **Final Phase 1 Procedure**

Step 1: Fill grout voids using vacuum grouting / vacuum assist grouting

Step 2: Drying process by blowing clean dry air to the tendons with soft grout. The drying is perform for the length of the to

mplete . Jne or both of following Drying is considered acceptable, provided m requirements:

- a. The average relative hur air from outlet ports has reached 20% or less.
- naximum of 40% moisture (required grout Jure level) b. The soft grout \uparrow

samples tr Step 3: Impregn Status Jcess can only begin after tendon drying is accepted. The impregnation pro ct is a Vector's proprietary product. The liquid injected is called Hydrocarbon and Silicon Polymer Inhibiting Impregnation Material. The corrosion inhibiting material is impregnated through the interstitial spaces between wires of a strand and the material travels from end to end of the tendon.



Repair Strategy

Phase 2 Repair Recommendations Add belt and suspenders: External tendons Status: On going Start: Summer 2019

We plan to present the Phase 2 Repair in 2020 Symposium


Repair Strategy



Elevation View - Phase 2 Repair Strategy - External Tendons



Repair Strategy



Typical Sections – - Phase 2 Repair Strategy - External Tendons





Tendon Mock-up



Grout Voids Injection





Tendon Impregnation Process – Contractor's Mock-up





Contractor's Mock-up

Tendon Inspection and Dissection

Grout cap





Salt spray testing on steel plate with untreated (left) and Post-Tech PTI treated section (right)

Salt spray testing on untreated (left) and Post-Tech PTI treated strand (right)





Tendon Impregnation

Post-Tech PTI flows along interstitial spaces in strands



Phase 1 Repair Construction Work platform under the bridge set up





Work platform under the bridge











Ground Penetrating Radar (GPR) for locating tendon









> Time to seal the clamp!!How hard could it be?!

Silicone + Clamp
Butyl tape + Clamp



Alright why is this not working.....

Weather Stripping (WS) + Clamp
Epoxy + Clamp
Epoxy + Clamp + Epoxy







6. Epoxy + WS + Clamp +Epoxy + Cure time + Bonding Agent + Concrete ☺





Drying process













Major Leak Zones



ELEVATION - SPANS 9, 10 & 11



-Air flow rate-Air temperature-Relative humidity



Phase 1 Repair Construction Air Sensors and Remote Monitoring Units (RMU'S)









œ

В

Flow (LPM)

7

1

0.7

0.3

3

2

0.3

0.5

2.5

0.3

0.3

2

SPAN 11

off to verify air is flowing continuously from the injection end, prior to using the vacuum pump. Pressurized air injection shall have a maximum relative humidity of 10%. The contractor is required to check the pressurized air injection flow rate and vacuum pump outlet relative humidity of air at least weekly or as directed by the Engineer. The drying of soft grout is considered acceptable if one or both of the following are met:

1. The average relative humidity of the air from the outlet ports has reached 20% or less.

2. The soft grout has a maximum moisture content of 40 % as approved by the Engineer from samples taken at locations along the length of the tendons as directed by the Engineer.

3. Clean and install the impregnation port(s) on the tendon location(s) determined in the field

decrease drying time. Dry each tendon section using pressurized air injection at one end and vacuum assistance at the opposite end. Install pressure gages and regulators at each air inlet with a required minimum pressure of 20 psi. Flow valves shall be installed at the vacuum outlet, and a required minimum air flow of 10 L/minute shall be maintained. Check air flow with vacuum pump assistance





But Wait....What About Those Leaks?





Tendon ID	Flow (LPM)
G1T1	7
G1T2	1
G2T1	0.7
G2T2	0.3
G3T1	3
G4T3	2
G4T4	0.3
G7T2	0.5
G7T4	2.5
G8T1	0.3
G8T2	0.3
G8T3	2

Sample ID	Avg Air Flow
	LPM
G1T1-11	3.75
G1T1-9	4.5
G1T2-11	4.7
G1T2-9	3.5
G2T1-11	2.3
G2T1-9	4
G2T2-11	2
G2T2-9	1.8
G3T1-11	6
G3T1-9	2
G4T3-11	2
G4T3-9	13
G4T4-11	3
G4T4-9	11
G7T2-9	22
G7T2-11	4.5
G7T4-9	12
G7T4-11	13
G8T1-9	13
G8T1-11B	5
G8T2-9	6
G8T2-11	7
G8T3-9	11
G8T3-11	12.5

Flow rate comparison End-to-end vs Center-out





Vacuum Pump Trial





Sample ID	Start Date 2018		Sept.	2018 Oct. 2018		Nov. 2018		Dec. 2018		Mid Jan			
	Mid July	Mid August	East Drying	West Drying	East Drying	West Drying	East Drying	West Drying	East Drying	West Drying	East Drying	West Drying	Total
	2018 - East	2018 West	Port	Port	Port	Port	Port	Port	Port	Port	Port	Port	Change
	Drying Port	Drying Port	Average	Average	Average	Average	Average	Average	Average	Average	Average	Average	
	Average	Average	RH%	RH%	RH%	RH%	RH%	RH%	RH%	RH%	RH%	RH%	
	RH%	RH%											
G1T1-11	66.00%		54.00%		51.00%		60.00%		37.00%		36.00%		30%
G1T1-9		63.00%		62.00%		65.00%		57.00%		54.00%		53.00%	10%
G1T2-11	68.00%		61.00%		61.00%		63.00%		59.00%		45.00%		23%
G1T2-9		57.00%		62.00%		62.00%		55.00%		54.00%		52.00%	5%
G2T1-11	75.00%		81.00%		71.00%		64.00%		54.00%		44.00%		31%
G2T1-9		55.00%		58.00%		58.00%		54.00%		49.00%		44.00%	11%
G2T2-11	76.00%		68.00%		70.00%		70.00%		65.00%		60.00%		16%
G2T2-9		57.00%		61.00%		62.00%		61.00%		53.00%		53.00%	4%
G3T1-11	41.00%		50.00%		54.00%		56.00%		49.00%		39.00%		2%
G3T1-9		48.00%		60.00%		57.00%		52.00%		51.00%		39.00%	9%
G4T3-11	53.00%		53.00%		47.00%		44.00%		45.00%		36.00%		17%
G4T3-9		27.00%		28.00%		25.00%		25.00%		23.00%		19.00%	8%
G4T4-11	69.00%		72.00%		72.00%		72.00%		67.00%		56.00%		13%
G4T4-9		34.00%		36.00%		32.00%		28.00%		28.00%		32.00%	2%
G7T2-9		31.00%		28.00%		22.00%		24.00%		24.00%		30.00%	1%
G7T2-11	80.00%		77.00%		82.00%		76.00%		80.00%		80.00%		0%
G7T4-9		21.00%		27.00%		24.00%		29.00%		27.00%		19.00%	2%
G7T4-11	62.00%		42.00%		49.00%		64.00%		33.00%		28.00%		34%
G8T1-9		41.00%		38.00%		37.00%		24.00%		23.00%		21.00%	20%
G8T1-11B	81.00%		94.00%		99.00%		62.00%		95.00%		90.00%		-9%
G8T2-9		57.00%		55.00%		54.00%		50.00%		60.00%		57.00%	0%
G8T2-11	68.00%		75.00%		79.00%		81.00%		85.00%		80.00%		-12%
G8T3-9		26.00%		35.00%		20.00%		?		19.00%		Injecting	7%
G8T3-11	74.00%		34.00%		34.00%		41.00%		29.00%		Injecting		45%





ELEVATION - SPANS 9, 10 & 11



Grout Sample Moisture Content

А

Air RH – 35%, Grout Sample – 10.8% wt

*RH – Relative humidity of outflow air Sample – Measured in % of water by weight (Moisture content)



Air RH – 35%, Grout Sample – 10.8% wt Air RH – 90%, Grout Sample – 7.9% wt

*RH – Relative humidity of outflow air Sample – Measured in % of water by weight (Moisture content)



Air RH – 35%, Grout Sample – 10.8% wt Air RH – 90%, Grout Sample – 7.9% wt Air RH – 50%, Grout Sample – 42.3% wt

*RH – Relative humidity of outflow air Sample – Measured in % of water by weight (Moisture content)



Phase 1 Repair Construction PTI Resin Injection Pump





Impregnation Set-up





ANDLING. TORAGE.

PHYSICAL DESCRIPTION: Liquid solution, fruity ester/amine like odor. HEALTH HAZARDS: Causes skin and eve burns: may be harmfu Causes skin and eye burns; may be harmful if absorbed through skin. Use in open air or with adequate ventilation. Wear PPE, see Section 8. Keep and to be paired at flames and other sources of ignition. Launder contaminated clothing. Keep containers tightly closed in a cool, well-ventilated place. Protect from moisture Reduit or might evolved might explode on ignition; do not apply heat, cut, drill, grind or weld on or near this contained



Field Injection Records

		A Low AT LAND					PARSONS
Contract: E2	V62 Wonder	wood Bridge 1	Fendon Impre	gnation Rec	ord		M. Bynyt
Tendon:	11 77			Avg Air flo	W LPIVI. J		
Tendon. C	9-15						
Inlet Locatio	ns: Span	#10 sta*	114				
Outlet Locat	ions: Spow	#9 stat	182				
Outlet Locat	Span	111 sta #	19	and contain	ner. 1" of c	lepth equa	Ils 1.57 liters of material.
Note: Inches	s of depth ar	e measured in	the pre-packa	Inches	Liters	PSI	Notes where each outlet
Date	Start	Stop	Time	9.5			Cont. bucket " 2 Vac pump com
1-21-19	9:10	1	9:40	9,25	0.39		
			10:13	9.0	0.39		
	3		10:45	8,75	0.39		
	4		11:15	8.625	0.2		
	X		11:45	B.315	0.31		
	1 10	1	12:12	0.0	029		
	130		12.42	7.75	0.39	110	
			1:45	7.25	0.79		
			2:15	7.25	0		
1-21-19		2:53		6.875	0,59		Stop
	1948						
		1-21-10 -	572 hrs		4.121		(0:72 L/hr DUMDING rate)
		1-21-19 =	2112112		TITLE		Port of the port o
	100 100 Sta		The second				
			Totals				
Vest End Anch	orage Treat	ment					
ast End Anchor	rane Treat	ont					
ast Linu Anchol	age freatm	ent					



Phase 1 Repair Construction Vacuum Pump Assistance for Injection




Phase 1 Repair Construction Impregnation process Outlet port

Inlet port









Phase 1 Repair Construction

4 Cables Injected
8 cables In progress
(Repairing leak
locations)



Closing

Project Credits

Phase 1 Repair Construction

Owner: FDOT District 2 (supported by SMO, SDO, D2 DSMO and D2 Construction) CE&I: Parsons Contractor: M&J Construction Sub-contractor for tendons repair: Vector Corrosion Technologies

Engineer of Record: Parsons Brinckerhoff (WSP)

Investigations Phase FDOT D2 / SMO TranSystems Concorr Florida Parsons Brinckerhoff (WSP) NDT Corporation (now part of Vector Corrosion Technologies)

